



iSys - The Imaging Systems Group Inc.  
911 - 28th Street NE Calgary, AB T2A 7X1  
t. 403.204.5200  
f. 403.204.1971  
w. [www.isys-group.com](http://www.isys-group.com)

## **PRINT DRIVER RELEASE NOTES**

<b>PRODUCT:</b>	<b>ITerra Lite</b>
<b>OPERATING SYSTEM:</b>	<b>Microsoft XP, Vista, Windows 7 : 32/64bit</b>
<b>RELEASED VERISON:</b>	<b>2.2</b>
<b>RELEASED DATE:</b>	<b>November 22, 2011</b>

### **iSys iTerra Lite Printer Driver 2.2**

- 1) Fixed spooler crash when selecting a new "Print Quality" mode.

### **iSys iTerra Lite Printer Driver 2.1**

- 1) Dot.Net printing support is added
- 2) Overrun on the Blue component compression is now fixed
- 3) Adjusted the 8.25" selected page to not include margins
- 4) Combined to a single installation for XP, Vista & Win7 on all 32 and 64 bit platforms

### **iSys iTerra Lite Printer Driver 2.0**

- 1) Support all current Windows operating systems (XP32, XP64, Vista32, Vista64)
- 2) Tested on Server 2003 & Server 2008, both 32 and 64 bit
- 3) Multi copy is added
- 4) Added 'Remove White Space' option from Top, Bottom or Top&Bottom of a page

### **iSys iTerra Lite Printer Driver 1.5**

- 1) Added standard iSys logo onto about tab
- 2) Fixed Multi-Copy print jobs greater than 10 pages
- 3) Changed fast normal mode to 300 dpi for faster throughput of iSys Continuous Paper.
- 4) Discarded small iSys logo on properties tabs

### **iSys iTerra Lite Printer Driver 1.3**

- 1) Fixed Test machine required page printing at driver installation
- 2) For Client-Server printing, client full access to iSys\_temp folder on the print server after driver installation.
- 3) No need to disable advanced printing features.

### **iSys iTerra Lite Printer Driver 1.0**

- 1) Fixed image-mirrored printing problem
- 2) Fixed the problem of hanging with MetaFile Viewer.

Any comments or questions regarding this document should be directed to:

**The Imaging Systems Group Inc.**  
Office: 403.204.5200  
Email: [support@isys-group.com](mailto:support@isys-group.com)