



Corporate Headquarters:

iSys - The Imaging Systems Group Inc.
911 - 28th Street NE Calgary, AB T2A 7X1

t. 403.204.5200 f. 403.204.1971

Visit us on-line: www.isys-group.com

V8.5 Product Notice

Sept.01/2005

Dear valued customer,

Please note, this does not pertain to V8.5e plotters.

Due to circumstances beyond our control, we are no longer able to produce V8.5 main boards. Unfortunately we cannot guarantee availability of the V8.5 main board, part# BD-8MAINASSY beyond Sept.01, 2007.

We will continue repairing V8.5 model printers after this date, but we cannot guarantee that they can be repaired if a new main board is required. In many cases we will be able to repair the damaged boards. All other parts will remain available.

If the unit cannot be repaired or you prefer our newer technology, we have arranged a special trade in program to upgrade to the improved V8.5e model. Upon purchase of a new model (and proof of owning a V8.5) we will discount your purchase by \$500. US.

Sincerely

Mark Hopkins
President